

DRAWING #	1
NAME OF OPERATOR :	
COURSE:	GRAD work / DR. MEDRAJ



TOOLS :
Staff Use Only

IN	9:00	OUT	10

EIR APPROVAL	
STAFF ASSIGNED	
MAT. RECEIVED	

Dr. Medraj

Operation #	Name Of Operation	Machine	Cutting Tool	Spindle Speed (RPM)	Comments	Risks / Hazards
1	Cutting	Saw	Band Saw	200 SPM	Cutting Cylindrical piece of Samples.	/



D.E. (WITH RESERVATION)

MISSING

?